

Model SD-6020

Force Gauge Datalogger



Instruction Manual

www reedinstruments com

Table of Contents

Features	3
Specifications	3-4
Instrument Description	5
Operating Instructions	6-10
Alarm Beeper	6
Peak Hold Measurement	6
Backlight ON/OFF	7
Datalogger	7
Auto Datalogger	7-8
Manual Datalogger	8
Peak Hold Datalogger	8-9
Checking the Time	
Check Sampling Time Information	9
SD Card Data Structure	
Data Transfer from SD card to Computer	9-10
Advanced Settings	10-12
SD memory card Format	11
Set Clock Time	11
Set sampling time	11
Set sampling time (Peak Mode)	11
Auto power OFF management	
Set Beeper Sound ON/OFF	
Setting the Decimal point on the SD Card	12
Set Measurement Unit	12
ESC	
PC Serial Interface	13
System Reset	
Battery Replacement	

Features

- Data record in Normal Mode or Peak Hold Mode
- Sampling time: Normal Mode: 1sec 8h; Peak Hold: 10ms 500ms
- Memory capacity: Normal Mode: 1GB 16 GB; Peak Hold: 1000 data no. (max)
- Display units in Kg, lb, Newton
- Tension and compression capability
- Full capacity zero (tare) control capability
- Fast/Slow response time
- Positive or reverse display direction
- Over load protection
- Real time SD memory card datalogger with a built-in clock and calendar
- No extra software needed, just plug the SD card into the computer and it downloads directly to EXCEL
- SD card capacity: 1 GB to 16 GB
- Easy to read LCD with backlight
- Auto power off or manual power off
- High accuracy microcomputer circuit
- Power by UM3/AA (1.5 V) x 6 batteries
- USB/RS232 Computer interface

Specifications

Circuit: Custom microprocessor LSI circuit Display: 52mm x 38mm LCD with backlight

Units: Kg, lb, Newton

Measuring Capacity: 20.00Kg / 44.10lb / 196.12N

Min. Display: 0.01Kg / 001lb / 0.02N

Accuracy: $\pm (0.5\% + 2 \text{ digits})$, within $23\pm5^{\circ}\text{C}$



Sampling Time: 0.2-0.6 seconds

Auto Sampling Time: 1 second to 9 hours

Peak Hold: 10mS - 500mS

Full Scale Deflection: 0.4mm Max

Zero/Tare Control: Max full capacity

SD memory card, 1 GB to 16 GB Memory Card: Data Output: USB/RS232 PC computer interface

Operating Temperature: 0-50°C (0-122°F)

Operating Humidity: Less than 85% R.H.

Power Supply: UM3/AA (1.5 V) x 6 batteries

Weiaht: 650a/1.43lb

Dimensions: 215 x 90 x 45mm (8.5 x 3.5 x 1.8")

Includes: Flat-head adapter, Hook adapter, Cone head

> adapter, Chisel head adapter, 120mm extension rod, and one Carrying case

Optional accessories: 2G SD Card (SD-2GB) Test stand (FS-1001)


Wedge grip (WG-01) USB cable (USB-01) RS232 cable (UPCB-01)


Data Acquisition Software (SW-U801-WIN)

Visit us at www.reedinstruments.com for more information on our Optional Accessories, or e-mail us at info@reedinstruments.com

For service on this or any other REED product or information on other REED products, contact REED Instruments at info@reedinstruments.com **Instrument Description**

- 1. Sensor
- 2. Display
- 3. Power & Backlight Button
- 4. Up & Zero Button
- 5. Fast, Slow, & ESC Button
- 6. Peak & Enter Button
- 7. Display Reverse
- & Down Button
- 8. Time & Set Button
- Logger & Sampling Check Button
- 10. USB/RS232 Output
- 11. Reset Button
- 12. AC/DC 9V Power Adapter Input Socket
- 13. Mounting Holes
- 14. Battery Compartment/Cover
- 15. Flat-head Adapter
- 16. Cone Adapter
- 17. Chisel Adapter
- 18. Hook Adapter
- 19, 120 mm Extension Rod
- 20. SD card slot







10

12

Operating Instructions

When measuring Compression, the meter will show a "-" symbol. While measuring, be sure to have the Sensor aligned with the object being measured. Do not measure on an angle, as the Sensor may be damaged and the readings will not be accurate.

- Turn on the meter by pressing the Power Button. To turn the meter off, hold the Power Button for 2 seconds.
- Select the measuring unit. For instructions on this, please see the Advanced Settings section.
- Connect an Adapter and the measuring object to the Sensor. The 3) measuring object should be in a straight line. Do not apply any force while in Standby Mode.
- 4) Zero Adjust the meter by pushing Zero Button before every measurement.
- Start measuring by giving force (push or pull) to the Sensor. The screen will display the Average reading value. To change the display direction, push the Reverse Button.
- There are two kind sampling time of display. Fast and Slow, The Display will indicate "FAST" if measuring in Fast Sampling Time, and "SLOW" if measuring under Slow Sampling Time. Push the Fast/Slow Button to switch between Fast and Slow Sampling.

Note: Over range of tension will display as " --- " and over range of compression will display as " ".

Peak Hold Measurement

The meter can measure the peak value of force both of tension & compression operation. While taking a measurement, as described above, press the Peak Button to switch to Peak Hold Mode. The Display will show the "PEAK" indicator, and during measurement the Display will freeze on the Peak hold value.

Alarm beeper

If the measuring value is over 20.00 Kg, an internal buzzer will sound.



Backlight ON/OFF

After powering the meter ON, the LCD Backlight will turn on automatically. While taking measurements, press the Backlight Button and the LCD Backlight will turn off. Press the Backlight Button once again to turn the LCD Backlight back ON.

Datalogger

Preparation Before Executing the Datalogger Function:

- Insert the optional SD card into the SD card socket.
- 2) Before you use an SD card with this meter for the first time, it is recommend to format the SD card. See Advanced Settings section of this manual for instructions.
- If this is the first time the meter is used you need to adjust the 3) clock. See Advanced Settings section of this manual for instructions.
- 4) Now you need to set the decimal format. The numerical data structure downloaded to the SD card is defaulted used the "." as the decimal, for example "20.6" "1000.53". But in certain countries the "," is used as the decimal point, for example "20, 6" "1000,53". See Advanced Settings section of this manual for instructions on how to change the Decimal Character.

Auto Datalogger (Set sampling time ≥1 second)

- Start Datalogging; press the REC Button, and the "REC" symbol will appear on the LCD screen, then press the Logger Button, the "REC" symbol will flash while the measuring data and time information is being saved in memory. To set the sampling time, and to togale the beeper sound on or off, refer to the Advanced Settings section of this manual.
- 2) Pause the Datalogging; while Datalogging, if press the Logger Button once. While paused, the "REC" symbol will stop flashing. Press the Logger Button again to resume Datalogging, and the "REC" symbol will begin to flash again.

continued...



3) Stop Datalogging; while the Datalogger function is paused, press the REC Button for 2 seconds. The "REC" symbol will disappear indicating the Datalogging function has stopped.

Manual Datalogger (Set sampling time = 0 seconds)

- 1) Set sampling time is to 0 second; Press the REC Button, and the "REC" symbol will appear on the LCD screen. Press the Logger Button, and the "REC" symbol will flash once and one Beep will sound, at the same time the measuring data along the time information will be saved in memory. The lower Display will show the Position (record) number, which is saved as well.
- To Change the Position Number; press the Down Button and the 2) lower position number will flash on the display. Press the Up or Down Buttons to set the Position Number (1 to 99) to help identify the measurement location. The lower Display will show P x (x = 1 to 99). After the position number is selected, press the Enter Button to confirm.
- Stop Datalogging; press the REC Button for 2 seconds, and the "REC" symbol will disappear indicating the Datalogging function has stopped.

Peak Hold Datalogger

- Install the meter on to the optional test stand and turn on the meter. 1)
- 2) Press the Peak Button and the Display will show "PEAK" & "FAST".
- 3) Press the Zero Button to set the Zero Value.
- Press the Logger Button and the screen will display "DATA 4) RECORD" while the sampling time value in ms will appear on the bottom of the screen. The meter is now ready for Peak Hold Datalogging.
- If the applied force value is > 0.2 Kg (1% full capacity), the 5) measurement value and sampling period will save to the internal memory circuit in sequence. To change the Sampling Time, please see the Advanced Settings section of this manual.

continued...



6) When the peak value is obtained, the indicator "DATA RECORD" will disappear, while the "PEAK" indicator and the Peak Value will remain. The bottom of the Display will show the data record number and count down to zero, while saving the data to the SD card.

Checking the Time

During normal functions (not Datalogging), press the Time Check Button and the lower LCD display will show the Year, Month/Date, Hour/Minute.

Check Sampling Time Information

During normal functions (not Datalogging), press the Sampling Button and the lower LCD display will show the Sampling Time Information.

SD Card Data Structure

- The first time the SD card is used in the meter, the SD card will generate a folder: FGB01
- 2) The first time you use the Datalogger, in the folder FGB01, a new file name FGB01001.XLS will be created. The Datalogger will use this file until the Data has reached to 30,000 rows. The meter will then will generate a new file with a subsequent number, for example FGB01002.XLS.
- The folder FGB01 can hold 99.XLS files. When that number has been reached, the meter will then will generate a new folder with a subsequent number, for example FGB02. Max number of FGB-folders is 10.

Data Transfer from SD card to Computer (EXCEL Software)

- 1) After Datalogging, remove the SD card from the SD card slot.
- 2) Plug in the SD card into the Computer's SD card slot or insert the SD card into the optional SD card adapter and connect to your Computer. Turn your computer on and a folder will appear on your desktop representing you SD card.

continued...



- 3) Open "Microsoft EXCEL". Download the EXCEL files from the SD Card to the computer by opening up the SD folder and selecting the desired EXCEL files, and drag-and-drop them onto your Computer. Open the files with EXCEL (File - Open).
- The EXCEL file will have the following column headers in this order: Place (Position Number), Date (Year/Month/Day), Time (in 24h clock), Value, and Unit.

Advanced Settings

During normal functions (not Datalogging), press and hold the SET Button for 2 seconds to enter the "Advanced Setting" mode. Press the Next Button scroll through eight main functions, shown on the lower display:

Sd F SD memory card Format

Set clock time (Year/Month/Date, Hour/Minute/Second) dAtE

SP-t Set sampling time (Hour/Minute/Second)

HSPt Set sampling time for peak record mode

PoFF Auto power OFF management

bEEP Set beeper sound ON/OFF unit Set the measurement unit dEC Set SD card Decimal character

ESC Exit Advanced Settings

While in the "Advanced Setting" function, press the Esc Button to exit and to return to normal functioning.

SD memory card Format

Please Note: Formatting the SD card erases all data from that SD card.

- 1) When the lower display shows "Sd F", use the Up or Down Buttons to select "yES" (format the SD card) or "no" (do not format the SD card).
- To format your SD card, select "vES" and press the Enter Button. The Display will show "yES Enter", to confirm. Press the Enter Button to confirm.



Set Clock Time

- 1) When the lower display shows "dAtE", press the Enter Button. Use the Up and Down Buttons to adjust the Year. After the desired value is set, press the Enter Button to adjust the Month, Date, Hour, Minute, and Second values.
- After all the time values have been set the screen will jump to "SD card Decimal character" setting screen. To exit "Advanced Settings", press the Esc Button.

Note: After the time value is set, the internal clock will run even when the power is off, if the battery is under normal conditions.

Set sampling time

- 1) When the lower display shows "SP-t", use the Up or Down Buttons to adjust the value to either 0, 1, 2, 5, 10, 30, 60, 120, 300, 600. 1800, or 3600 seconds.
- 2) After the Sampling value is selected, press the press the Enter Button to save the setting as the default. To exit "Advanced Settings", press the Esc Button.

Set sampling time (Peak Mode)

- 1) When the lower display shows "HSPt", use the Up or Down Buttons to adjust the Sampling Time value between 10mS and 500mS.
- After the Sampling value is selected, press the press the Set Button to save the setting. To exit "Advanced Settings", press the Esc Button.

Auto power OFF management

- 1) When the lower display shows "PoFF", use the Up or Down Buttons to select the value "yES" (Enable Auto Power Off) or "no" (Disable Auto Power Off.
- 2) After selecting "yES" or "no", press the Enter Button to save the setting as the default. To exit "Advanced Settings", press the Esc Button.



Set Beeper Sound ON/OFF

- 1) When the lower display shows "bEEP", use the Up or Down Buttons to select "vES" (Beeper Sound is ON) or "no" (Beeper Sound is OFF).
- After selecting "yES" or "no", press the Enter Button to save the setting as the default. To exit "Advanced Settings", press the Esc Button.

Setting the Decimal point on the SD Card

- 1) When the lower display shows "dEC", use the Up or Down Buttons to toggle between "bASIC" ("." Decimal Point) or "Euro" ("," Decimal Point).
- 2) After the Decimal point character has been selected, press the Enter Button to save the setting as the default. To exit "Advanced Settings", press the Esc Button.

Set Measurement Unit

- 1) When the lower display shows "unit", use the Up or Down Buttons to adjust the measurement unit. Kg. lb. or N.
- After the Measuring Unit is selected, press the press the Enter Button to save the setting. To exit "Advanced Settings", press the Esc Button

FSC.

When the lower display shows "ESC", press the Enter Button to finish the Advanced Settings procedures and return to the normal measuring screen.

PC Serial Interface

The instrument features an PC output via 3.5 mm terminal. The connector output is a 16 digit data stream which can be utilized to the user's specific application. An USB RS232 lead with the following connection will be required to link the instrument with the PC serial input.

Meter (3.5mm Jack Plug)	PC (9W "D" Connector)
Center Pin	Pin 2
Ground/Shield	Pin 5

The 16 digit data stream will be displayed in the following format: D15 D14 D13 D12 D11 D10 D9 D8 D7 D6 D5 D4 D3 D2 D1 D0

D0	End Word
D1 to D4	Upper Display reading, D1= LSD, D4= MSB
D5 to D8	D5=? D6=? D7=? D8=?
D9	Decimal Point (DP) for display 0 = No DP, 1 = 1 DP, 2 = 2 DP, 3 = 3 DP
D10	D10 = 0
D11	D11 = 0
D12	D12 = 0
D13	D13 = 0
D14	D14 = 0
D15	Start Word

System Reset

If an error occurs, press the Reset Button with a Pin. If the Reset Button does not fix the error, please send in the unit to our Calibration Lab for repair. E-mail info@reedinstruments.com for more information.

Battery Replacement

- 1) When the left corner of LCD display shows A, it is necessary to replace the battery
- Loosen the screws of the Battery Cover and remove 2)
- Remove the batteries and replace with Six DC 1.5 V batteries 3) (UM3, AA, Alkaline/heavy duty)
- Make sure the battery cover is properly secured after changing the battery

For service on this or any other REED product or information on other REED products, contact REED Instruments at info@reedinstruments.com

Notes _	 	 	



Notes _	 	 	

